

# Healix Enterprises Operating Guidelines for the E-Zcut II™ Freestanding Pineapple Peeling & Coring Machine

*Remember: Nothing replaces common sense, ensure a safe working environment when operating any type of cutting equipment.*

1. The cutting blades are very sharp! Always use caution when operating this machine.
2. Cut top and bottom off parallel to each other. (Make sure to cut enough off so that the blade will begin the cut on the exposed meat of the pineapple)
3. Using your right hand lift the grip of the handle up to maximum height (Pull the handle back towards yourself and lift)
4. Place the pineapple under the push plate and slowly lower the handle, making sure to center the outside blade to the center of the cut pineapple. (push the handle away from yourself and down)
5. Place two hands on the handle and firmly push down until the push plate makes contact with the blades.
6. Lift the handle up. This will lift the peeled and cored pineapple through the blade and set it on the top of the blade.
7. With your hand still on the handle! Remove the peeled and cored pineapple.
8. Caution, cutting assemblies are very sharp. Never put your hands under the push plate without one hand on the handle, and never hold the pineapple when you are cutting the pineapple.
9. Properly hand wash, rinse, and sanitize. (Following your local health code standards)

## Sanitation Assurance™ (SA)

- All materials intended for direct food contact are NSF accepted or FDA certified
- Materials Safety Data Sheets Available: [www.pineappleking.com](http://www.pineappleking.com)

# HEALIX

## Design and Manufacturing

Visit Us On the Web: [www.pineappleking.com](http://www.pineappleking.com)

Call Us: Phone/Fax: 812-282-9869